

TechCon: Conference for the Maintenance and Operation of High-Voltage Electrical Equipment 2011

(TechCon 2011)

**San Francisco, California, USA
25-28 January 2011**

ISBN: 978-1-61782-962-8

Printed from e-media with permission by:

Curran Associates, Inc.
57 Morehouse Lane
Red Hook, NY 12571



Some format issues inherent in the e-media version may also appear in this print version.

Copyright© (2011) by the TJ/H₂b Analytical Services, Inc.

All rights reserved.

Printed by Curran Associates, Inc. (2011)

For permission requests, please contact the TJ/H₂b Analytical Services, Inc.
at the address below.

TJ/H₂b Analytical Services, Inc.
3123 Fite Circle
Sacramento, CA 95827

Phone: (916) 361-7177
Fax: (916) 361-7178

li@tjh2b.com

Additional copies of this publication are available from:

Curran Associates, Inc.
57 Morehouse Lane
Red Hook, NY 12571 USA
Phone: 845-758-0400
Fax: 845-758-2634
Email: curran@proceedings.com
Web: www.proceedings.com

TABLE OF CONTENTS

138 kV Potential Transformer Failures of February 18, 2006	1
<i>S. Adams</i>	
500kV Bushing Failure Root Cause Analysis at Tennessee Valley Authority	22
<i>M. Goff</i>	
Don't become a Victim of an LTA PdM Program	36
<i>J. Giesecke</i>	
Natural Ester Dielectric Coolants for Small, Medium & Large Power Class Transformers	59
<i>P. McShane</i>	
OLTC Dynamic Testing	70
<i>R. Levi, B. Milovic</i>	
Paper Ageing & Transformer Life	86
<i>K. Budin</i>	
Point Woronzof Reactor Failure Case Study	122
<i>S. Girard</i>	
Practical Considerations in Applying Monitoring Systems on Power Transformers	150
<i>D. Bates, G. Hoffman, J. Watson</i>	
Premature Failure of Electrical Equipment & Oil Analysis	166
<i>E.R. Crutcher, K. Warner</i>	
Synthetic Esters as Dielectric Fluids for Transformers: Properties and Perspectives	179
<i>G. Goujon</i>	
Tertiary Delta Winding for Y-Y Connected Transformers	197
<i>S. Patel</i>	
Author Index	