

The Electrochemical Society

Corrosion of Infrastructure

at the 210th ECS Meeting

ECS Transactions Volume 3 No.13

October 29 – November 3, 2006
Cancun, Mexico

Printed from e-media with permission by:

Curran Associates, Inc.
57 Morehouse Lane
Red Hook, NY 12571
www.proceedings.com

ISBN: 978-1-60423-367-4

Some format issues inherent in the e-media version may also appear in this print version.

Table of Contents

Preface

Chapter 1 **Cementitious Systems - Service Life**

Critical Review of Service Life Concepts of Reinforced Concrete Structures <i>J. Mendoza-Rangel and P. Castro-Borges</i>	3
Service Life of Reinforced Concrete Structures. New Approach <i>P. Castro-Borges and P. Helene</i>	9
Structural Assessment of Corroded Beams <i>M. Prieto, A. Muñoz Noval and M. Andrade Perdriz</i>	15
Relation between Crack Width and Diameter of Rebar Loss Due to Corrosion of Reinforced Concrete Members <i>A. Muñoz Noval, C. Andrade, A. Torres and J. Rodríguez</i>	29
Electrochemical Measurements in Cement Extract Solutions on Reinforcing Steel, Previously Conditioned in Concrete <i>D. Koleva, J. de Wit, K. van Breugel, V. Bachvarov, H. Kolev and A. Fraaij</i>	37

Chapter 2 **Cementitious Systems - Corrosion Resistant Reinforcement; Cathodic Protection**

Corrosion Propagation Behavior of New Metallic Rebar Materials in Simulated Concrete Environments and Engineering Implications <i>M. F. Hurley and J. Scully</i>	53
Monitoring the Corrosion Behavior of Coated Reinforcement for Concrete <i>H. G. Wheat and G. Liu</i>	71
Coating Condition Evaluation of Epoxy Coated Rebar <i>K. Lau and A. A. Sagüés</i>	81

Cathodic Protection in Reinforced Concrete Elements, using Carbon Fibers Base Composites	93
<i>F. Lee-Orantes, A. A. Torres-Acosta, M. Martínez-Madrid and C. López-Cajún</i>	

Modeling the Polarization Behavior of a Galvanic Point Anode - Reinforcing Steel in Concrete System	99
<i>M. J. Dugarte, A. A. Sagüés and R. Powers</i>	

Chapter 3 **Cementitious Systems - Monitoring**

The Use of Polarization Resistance to Evaluate the Environmental Impact on Reinforced Concrete Structures in the Iberoamerican Region	111
<i>O. M. Troconis de Rincón, C. Andrade, M. Barboza, F. Irassar, J. C. Montenegro, R. Vera, A. M. Carvajal, R. M. de Gutierrez, S. Delvasto, E. Saborio, A. A. Torres-Acosta, J. Perez-Quiroz, F. Almeraya, P. Castro-Borges, E. I. Moreno, T. Perez-Lopez, W. Martinez, M. Salta, A. P. de Melo, I. Martinez, M. Castellote, G. Rodriguez, M. Derregibus, M. Sanchez, E. A. de Partidas and V. Millano</i>	

Corrosion-Related Failure of Post Stressed Tendons	117
<i>D. Tromans</i>	

Electrochemical Noise Corrosion Monitoring of Post Tensioned Tendons	129
<i>L. Taveira, B. Joseph and A. A. Sagüés</i>	

Electrochemical Evaluation of Galvanized Rebars in Alkaline Solutions with an Inhibitor	139
<i>M. J. Herrera, A. A. Torres-Acosta, J. T. Perez and M. Martinez</i>	

Chapter 4 **Natural and Industrial Media**

Galvanic Behavior of Type 2 Aluminized Steel in Simulated Natural Waters	147
<i>L. Caseres and A. A. Sagüés</i>	

Runoff-Induced Atmospheric Corrosion of Zinc	159
<i>E. A. Meraz, L. P. Veleza and M. A. Acosta</i>	

Chapter 5

Pipelines; Coatings

The Influence of Inclusions and Naphthenic Acids on the Corrosion of Pipeline Steels <i>P. Schütz, & L. Castilhos, L. Rodrigues and L. P. Dick</i>	173
Electrochemical Characterization of X80 Steel under Sour Environments and Addition of Imidazoline Based Compounds Under Linear Flow Conditions <i>R. Hernandez, M. Galicia and H. Castaneda</i>	181
Biocomplexity and Bioelectrochemical Influence of Anaerobic Biofilms in Gasoline Distribution Pipelines <i>X. Dominguez Benetton and D. Ramírez Espinosa</i>	199
Author Index	213