

# **TechCon: Conference for the Maintenance and Operation of High-Voltage Electrical Equipment 2010**

**(TechCon 2010)**

**Ponte Vedra, Florida, USA  
1 – 3 March 2010**

**ISBN: 978-1-61738-318-2**

**Printed from e-media with permission by:**

Curran Associates, Inc.  
57 Morehouse Lane  
Red Hook, NY 12571



**Some format issues inherent in the e-media version may also appear in this print version.**

Copyright© (2010) by the TJ/H<sub>2</sub>b Analytical Services, Inc.

All rights reserved.

Printed by Curran Associates, Inc. (2010)

For permission requests, please contact the TJ/H<sub>2</sub>b Analytical Services, Inc.  
at the address below.

TJ/H<sub>2</sub>b Analytical Services, Inc.  
3123 Fite Circle  
Sacramento, CA 95827

Phone: (916) 361-7177

Fax: (916) 361-7178

[li@tjh2b.com](mailto:li@tjh2b.com)

**Additional copies of this publication are available from:**

Curran Associates, Inc.  
57 Morehouse Lane  
Red Hook, NY 12571 USA  
Phone: 845-758-0400  
Fax: 845-758-2634  
Email: [curran@proceedings.com](mailto:curran@proceedings.com)  
Web: [www.proceedings.com](http://www.proceedings.com)

# TABLE OF CONTENTS

<b>Assessment of Gapless MOV Arrester Condition Using Resistive Leakage Current Measurements</b> .....	1
<i>J. McBride</i>	
<b>Asset Management-End of Life Decision Making in Power Transformers</b> .....	16
<i>T. Breckenridge</i>	
<b>Bushing Selection-"Making the Right Choice"</b> .....	36
<i>K.P. Ellis</i>	
<b>Circuit Breaker Overview- Specification Installation Maintenance Diagnostic Testing Troubleshooting</b> .....	49
<i>J. Ames</i>	
<b>Cooling System Optimization</b> .....	61
<i>V. Vailoor</i>	
<b>Copper Mobility and Failure in Electrical Equipment-It is not Corrosive Sulfur</b> .....	69
<i>E.R. Crutcher, K. Warner</i>	
<b>Determination of Health Index for Aging Transformers in View of Substation Asset Optimization</b> .....	92
<i>B. Sparling, J. Aubin</i>	
<b>Effects of Low Oil Level in a Bushing</b> .....	108
<i>M.B. Goff</i>	
<b>Environmentally Sustainable and Fire Resistant Power Transformers</b> .....	120
<i>G.J. Pukel, R. Schwarz, F. Baumann, H. Pocheim</i>	
<b>Field Results of Monitoring Partial Discharge Measurements on In-Service Large Power Transformers</b> .....	134
<i>C. Kane, A. Golubev</i>	
<b>Influential Variables on the Aging of Cellulose for Transformers with Oil Cellulose Insulation</b> .....	150
<i>C. Kuen, M. Scala</i>	
<b>Review of Recent Changes to Mineral Insulating Oil Specifications</b> .....	164
<i>S. Krawiec</i>	
<b>Substation Metalclad Assessment Using Handheld Ultrasonic and Transient Earth Voltage Testing Devices</b> .....	174
<i>J.M. Garnett, J.E. Gavin, A.J. McGrail, T.J. Miles</i>	
<b>Successful Hydrogenation of Used Naphthenic Oil</b> .....	187
<i>M. O'Neill</i>	
<b>Utilizing Piecewise Linear Approximation and Harmonic Regression to Analyze Power Transformer Insulating Oil Online Dissolved Gas Samples</b> .....	198
<i>D. Lamontagne</i>	
<b>Author Index</b>	