

# **Recent Advances in Maintenance and Repair of Concrete Bridges**

**Papers Presented at the ACI Spring 2010 Convention  
ACI SP 277**

**Chicago, Illinois, USA  
21 – 25 March 2010**

**Editors:**

**Yail J. Kim**

**ISBN: 978-1-61839-205-3**

**Printed from e-media with permission by:**

Curran Associates, Inc.  
57 Morehouse Lane  
Red Hook, NY 12571



**Some format issues inherent in the e-media version may also appear in this print version.**

Copyright© (2010) by the American Concrete Institute  
All rights reserved.

Printed by Curran Associates, Inc. (2011)

For permission requests, please contact the American Concrete Institute  
at the address below.

American Concrete Institute  
38800 Country Club Drive  
Farmington Hills, MI 48333 USA

Phone: (248) 848-3700  
Fax: (248) 848-3701

BKStore@concrete.org

**Additional copies of this publication are available from:**

Curran Associates, Inc.  
57 Morehouse Lane  
Red Hook, NY 12571 USA  
Phone: 845-758-0400  
Fax: 845-758-2634  
Email: [curran@proceedings.com](mailto:curran@proceedings.com)  
Web: [www.proceedings.com](http://www.proceedings.com)

## TABLE OF CONTENTS

### **SP-277-1**

Seismic Rehabilitation of RC Bridges by Using FRP and SRP:	
Case Study of a Bridge in the South of Italy .....	1-20
by R. Cuzzilla, M. Di Ludovico, A. Prota, and G. Manfredi	

### **SP-277-2**

Performance Evaluation and Maintenance of Concrete Bridges in Cold Regions.....	21-38
by A. Hmidan, Y.J. Kim, D.K. Yoon, and S. Yazdani	

### **SP-277-3**

TEXAS' Use of CFRP to Repair Concrete Bridges.....	39-57
by D. Yang, B.D. Merrill, and T.E. Bradberry	

### **SP-277-4**

Evaluation of Fire-Damaged Bridges: A Case Study .....	58-66
by S.T. Wyatt	

### **SP-277-5**

Improving Preventive Bridge Maintenance.....	67-78
by J.L. Silfwerbrand	

### **SP-277-6**

FRP Retrofit for a Historic Arch Bridge in Southern Ontario .....	79-88
by S. Davis, C.B. Laaber, and K. Soudki	

### **SP-277-7**

Design Considerations in the Rehabilitation of a Historic Arch Bridge across the Tennessee River in Knoxville, Tennessee.....	89-108
by Satrajit Das	

### **SP-277-8**

Nondestructive Evaluation Techniques and Acoustic Emission for Damage Assessment of Concrete Bridge in Marine Environment.....	109-128
by A.B. Suma, R.M. Ferraro, B. Metrovich, F. Matta, and A. Nanni	

### **SP-277-9**

Inspection Techniques for a Damaged Prestressed Concrete Girder Bridge: A Case Study .....	129-142
by Y.J. Kim, R.G. Wight, and M.F. Green	

### **SP-277-10**

Case Study in the Evaluation and Repair of ASR Deterioration in Concrete Bridge Beams .....	143-155
by M.E. Williams and D. Choudhuri	

SP-277-11

Laboratory Investigations on the Repair of GFRP-Reinforced  
Concrete Bridge Deck Slabs..... 156-175  
by E. El-Salakawy, A. Mufti, and A. Elragaby

SP-277-12

CFRP Repair of Corroded Girder: Four Years of Service ..... 176-191  
by A. Rteil and K. Soudki