

6th Congress on Forensic Engineering 2012

Gateway to a Safer Tomorrow

**San Francisco, California, USA
31 October – 3 November 2012**

Volume 1 of 2

Editors:

**Anthony M. Dolhon
Michael J. Drerup
Alicia Díaz de León**

**Joshua B. Kardon
Derrick S. Hancock
Shen-en Chen**

ISBN: 978-1-62276-652-9

Printed from e-media with permission by:

Curran Associates, Inc.
57 Morehouse Lane
Red Hook, NY 12571



Some format issues inherent in the e-media version may also appear in this print version.

Copyright© (2012) by the American Society of Civil Engineers
All rights reserved.

Printed by Curran Associates, Inc. (2013)

For permission requests, please contact the American Society of Civil Engineers
at the address below.

American Society of Civil Engineers
1801 Alexander Bell Drive
Reston, VA 20191

Phone: (800) 548-2723
Fax: (703) 295-6333

www.asce.org

Additional copies of this publication are available from:

Curran Associates, Inc.
57 Morehouse Lane
Red Hook, NY 12571 USA
Phone: 845-758-0400
Fax: 845-758-2634
Email: curran@proceedings.com
Web: www.proceedings.com

TABLE OF CONTENTS

VOLUME 1

AWARDS: ASCE TECHNICAL COUNCIL ON FORENSIC ENGINEERING

Awards: ASCE Technical Council on Forensic Engineering	1
<i>Kenneth L. Carper</i>	

BRIDGES I: INSPECTION AND RATING, STRUCTURAL HEALTH MONITORING, AND ASSESSMENT

Inspection and Rating of the Platte River Bridge in Denver	8
<i>Rui Liu, Kevin L. Rens</i>	
Use of a Structural Health Monitoring System for the Assessment of Bridge Load Rating	18
<i>Junwon Seo, Brent M. Phares, Ping Lu, Terry J. Wipf, Justin Dahlberg</i>	
Structural Health Monitoring with Interferometric Radar	28
<i>Paul James Bennett, Frederick R. Rutz</i>	
Visual Information Processing for Status Assessment in Bridges	38
<i>Natarajan Meenu, A. R. Rajaram, C. Natarajan</i>	

BRIDGES II: FORENSIC INVESTIGATION MODELING, BRIDGE FALSEWORK, REINFORCED CONCRETE BRIDGES, AND COLLAPSE

Forensic Investigation Modeling (FIM) Approach: I35 West Bridge Collapse Case Study	48
<i>F. Brando, A. Iannitelli, L. Cao, E. A. Malsch, G. Panariello, J. Abruzzo, M. J. Pinto</i>	
Collapse of Robinson Road Bridge Falsework	58
<i>R. A. Dethlefs, Z. Martin</i>	
Failure of Reinforced Concrete Bridges in California	65
<i>K. K. Sasaki, T. F. Paret</i>	
Statistical Analysis of the Causes of Bridge Collapse in China	75
<i>Zhongqiu Fu, Bohai Ji, Miao Cheng, Hirofumi Maeno</i>	

BRIDGES III: CURVED STEEL BRIDGES, REINFORCEMENT WITH FRP, STRUCTURAL INVESTIGATION, AND BRIDGE CABLES

Influential Curved Steel Bridge Fragility Analysis Parameters	84
<i>Junwon Seo, Daniel G. Linzell</i>	
Failure Analysis of Bridges Span Reinforced with FRP: A Computer Simulation	93
<i>A. Sabamehr, N. Amani</i>	
Structural Investigation of the Sherman Minton Bridge Closure	103
<i>Lisa Davey, Sara Jozefiak, Jimmy Lau, J. Abruzzo, G. Panariello</i>	
Restrained Bending Fatigue Design of Bridge Cables	113
<i>S. W. Khan, M. Raoof</i>	

BUILDING ENVELOPE I: GLAZING AND CURTAIN WALL SYSTEMS

Review of the Performance of Glazing Systems in Earthquakes and Recent Developments to Mitigate Damage	123
<i>A. Memari</i>	
Mitigating the Injuries from Flying Glass Due to Air Blast	133
<i>Hossein Ataei, James Anderson</i>	
Thermal Breakage of Spandrel Glass: A Case Study	143
<i>James Triano, John Cocca</i>	
WilTel Technology Curtain Wall Framing Failure Investigation	151
<i>D. A. Wojnowski, C. R. Fischer</i>	

BUILDING ENVELOPE II: COMPOSITE FOAM PANELS, SHINGLE ROOFS, RESIDENTIAL CONSTRUCTION, AND LARGE SCALE BUILDING ENVELOPES

Potential Problems Arising from the Use of Composite Foam Panels on Sloping Roofs	161
<i>Leonard J. Morse-Fortier</i>	

Guidelines to Assess Hail Damage to Shingle Roofs	169
<i>B. East, T. Lozos, S. Verhulst, M. DeLeon, D. Ahuja</i>	
The Hamptons at MetroWest: A Case Study of an Investigation into the Causes for Structural Rot Damage	179
<i>Felix Martin</i>	
Investigating Large Scale Building Envelope Leakage: Ten Practical Tips for Litigation Projects	190
<i>C. L. Searls, T. N. Stubblefield</i>	

BUILDING ENVELOPE III: TERRA COTTA MASONRY, FACADE REPAIRS, AND SOLID MASONRY

Identifying Non-Catastrophic Failures in Glazed Architectural Terra Cotta Masonry	201
<i>T. A. Gentry</i>	
Repair of a Landmark Building’s Facade: 230 Park Avenue, New York, NY	210
<i>Robert Nacheman, Jun Yu, Kunal Badheka</i>	
Investigation and Remedial Strengthening of Deteriorated Masonry Walls	220
<i>Amy S. Graver, Charles J. Russo, Michael L. Brainerd</i>	
Investigation and Repairs of a Leaning Historical Bell Tower	229
<i>Prasad M. Samarajiva, Narendra Gosain</i>	

BUILDING ENVELOPE IV: CELLULOSE INSULATION, STUCCO TRIM, AND COMPOSITE WOOD PRODUCTS

Potential Pitfalls of a Green Building Material: A Case Study of Cellulose Insulation	239
<i>D. Ahuja, B. Smith, Gregory G. Schober, M. DeLeon</i>	
Casing the Joint: Cutting Corners with Stucco Trim \neq Waterproofing Flashing	250
<i>Robert Bateman, Rene Luft</i>	
Interpreting Continuous v. Repeated Water Damage	260
<i>R. E. Moon</i>	

CRITICAL INFRASTRUCTURE I: ASBESTOS-CEMENT PIPE, CONTAINMENT DIKE, HDPE PIPE, AND NON-CIRCULAR TUNNEL

Asbestos-Cement Pipe Condition Assessment and Development of Optimum Replacement Methodology	268
<i>N. J. Harris, M. Radlinski</i>	
Instability of a Fly Ash Pond Containment Dike in Eastern India	280
<i>Debasis Roy, Raghvendra Singh</i>	
A Case Study of a Ground Slip during the Installation of an HDPE Pipe	286
<i>L. S. Bryson, C. L. Yohe, D. Hinkle</i>	
Wedge Stability in the Roof of a Non-Circular Tunnel	296
<i>Hang-Zhou Li, Hong-Jian Liao, Xianlun Leng</i>	

CRITICAL INFRASTRUCTURE II: RAPID DAMAGE ASSESSMENT, EARTHQUAKE-INDUCED STEEL FRACTURE, AND NATURAL GAS SYSTEMS

The February 2011 Christchurch Earthquake: Incorporating Transect Methodology into Rapid Damage Assessment	306
<i>L. M. Moon, D. T. Biggs, J. M. Ingham, M. C. Griffith</i>	
A Framework for the Forensic Examination of Earthquake-Induced Steel Fracture Based on the Field Failures in the 2011 Christchurch Earthquake	314
<i>D. A. Grilli, K. Marshall, A. M. Kanvinde</i>	
Post-Earthquake Checklist for Natural Gas Systems	324
<i>Peter W. McDonough</i>	

CRITICAL INFRASTRUCTURE III: TECHNICAL RESPONDER TRAINING, CRANE COLLAPSE, LASER SCANNING, AND LEGAL AND INSURANCE ISSUES

Structural Engineering Training and Experience Requirements at an Origin and Cause Scene Scenario with Subsequent Crane Collapse	333
<i>Douglas L. Fell</i>	
51st Street Crane Collapse: Issues in the Investigation during Criminal Proceedings	342
<i>James S. Cohen</i>	

Laser Scanning at an Origin and Cause Scene Scenario with Subsequent Crane Collapse	351
<i>Douglas L. Fell, Vladimir Scheglowksi</i>	
Common Legal Doctrines and Insurance Issues Affecting the Forensic Structural Engineer	358
<i>David J. Taylor</i>	

DESIGN PRACTICES: DESIGN FOR SAFETY, COORDINATION RESPONSIBILITIES, ENGINEER’S RESPONSIBILITIES, AND CIVIL ENGINEER’S ROLE IN ACCESSIBILITY

Application of Visualization Technologies to the Design for Safety Concept	370
<i>Mohammad Kasirossafar, Farzad Shahbodaghlou</i>	
Failure to Communicate: Risks of Independently Retained Design Professionals.....	378
<i>Robert C. Haukohl, W. Joseph Macicak</i>	
An Engineer's Responsibility in the Design and Detailing of a Structure's Lateral Force Resisting System: A Case Study.....	388
<i>Daniel M. Killian, Kerry S. Lee</i>	
The Civil Engineer's Role in Mitigating ADA Disputes in California.....	398
<i>Kenneth J. Pinnegar, Fred Pinnegar</i>	

DISASTER RISK MANAGEMENT: CRITICAL STRUCTURAL SAFETY FACTORS, URBAN PUBLIC INFRASTRUCTURE, MITIGATION ASSESSMENT TEAM, AND CASE STUDIES

Possible Critical Structural Safety Factors: A Literature Review.....	408
<i>Karel Terwel, Jan Vambersky</i>	
Agent-Based Risk Assessment and Mitigation for Urban Public Infrastructure	418
<i>Gabriela M. Atanasiu, Florin Leon</i>	
FEMA Mitigation Assessment Team Program	428
<i>John Ingargiola, Manuel Perotin</i>	
Corps of Engineers Forensic Studies.....	438
<i>P. F. Mlakar, J. C. Ray, V. P. Chiarito</i>	

EDUCATION: FAILURES EDUCATION AND FAILURE CASE STUDIES IN THE CIVIL ENGINEERING CURRICULUM

Creating Better Buildings through Failures Education: Wikis, Forums, Synths, Tweets, Case Studies, and Discussion Posts.....	448
<i>M. Kevin Parfitt</i>	
Implementation and Assessment of Failure Case Studies in the Engineering Curriculum.....	458
<i>Norbert J. Delatte, Paul A. Bosela, Joshua Bagakas</i>	
Introducing Case Studies in the Civil Engineering Curriculum of Tongji University, China.....	467
<i>Kaoshan Dai, Xiaosong Ren, Wensheng Lu, Chao Liang</i>	

EMERGING TECHNOLOGIES: 3D LIDAR SCANNING AND SMART PHONE APPLICATIONS

Post-Earthquake and Tsunami 3D Laser Scanning Forensic Investigations.....	477
<i>Michael J. Olsen, Robert Kayen</i>	
3D LiDAR Scans for Bridge Damage Evaluation	487
<i>Shen-En Chen, Wanqiu Liu, Haitao Bian, B. Smith</i>	
Damage Evaluation Using LiDAR Scan and Smart Piezo Layer.....	496
<i>Shen-En Chen, Howard Chung, Youngjin Park, Shannon Bell, Alex Deaton</i>	
Opportunities and Considerations for Smartphone Applications and Mobile Social Media in Post Extreme Event Reconnaissance Data Collection.....	505
<i>Heidi Michelle Bland, J. David Frost</i>	

FIRES: CHLORINE GAS RELEASE, FIRE SPRINKLERS, AND DAMAGE EVALUATION

Investigation of a Chlorine Gas Release Caused by the Mixing of Incompatible Chemicals	515
<i>Russell Ogle, Suzanne Smyth, Andrew Carpenter</i>	
Investigating Inadvertent Automatic Fire Sprinkler System Discharges.....	525
<i>A. F. Blum, R. T. Long Jr., S. E. Dillon</i>	
Fire Damage Evaluation for Residential and Commercial Buildings.....	535
<i>James W. Jordan, Marc A. Sokol, John H. Stewart</i>	
Analyzing Unsatisfactory Fire Sprinkler Performance.....	547
<i>A. F. Blum, R. T. Long Jr., N. P. Wu, S. E. Dillon</i>	

FLOODS: RESIDENTIAL STRUCTURES, WATERMARKS, DAMAGE-RESISTANT MATERIALS, AND WIND AND WAVE ACTION

Flood Damage Evaluation for Residential Structures 556
James W. Jordan, Craig D. Rogers

Use of Watermarks for Discerning Hurricane-Induced Flood Levels 568
Erik L. Nelson

Draft Standard for Flood Damage-Resistant Materials 575
John Ingargiola, Julia Moline

A Case Study of the Impact of Wind and Wave Action on Floating Dock Anchorage Systems on Lake Brownwood, Texas 585
David C. Jones, M. DeLeon, Matthew L. Breidenthal, Kurt W. Cady

FLOORING: FINISHED QUALITY, CARPET TACK STRIPS, ENGINEERED WOOD, AND CERAMIC TILE SYSTEMS

Using ASTM E1155 to Determine Finished Floor Quality: Background and Areas for Consideration 595
Patxi Uriz, John Osteraas, B. McDonald

Using ASTM E1155 to Determine Finished Floor Quality: Minimum Sampling Requirements Used to Establish Compliant Floor Flatness and Levelness 605
Duane Steffey, Patxi Uriz, John Osteraas

Carpet Tack Strips: Determining the Duration of a Water Loss 613
Donald E. Nehrig, R. E. Moon

Trouble Underfoot—In Situ and Laboratory Investigation of Engineered Wood Flooring 621
Michael J. Drerup, Ibrahim Erdem, Ronald W. Anthony

Common Perils of Ceramic Floor Tile Systems 631
Bart B. Barret, James M. Falls

GEOTECHNICAL I: MECHANICALLY STABILIZED EARTH, TUNNEL HEAVE, PARTIALLY SATURATED SOILS, AND BEARING CHARACTERISTICS

Look Out Below! Potential Pitfalls and Suggested Improvements in the Design and Construction of Mechanically Stabilized Earth (MSE) Walls 641
Scott J. DiFiore, Bryan P. Strohman

Theoretical Analysis on Underlying Tunnel Heave during a New Pit Construction 651
Ping Li, Tao Yu, Hanlong Liu, Xingde Zhou

Forensic Evaluation on the Bearing Capacity of Partially Saturated Soils—A Heuristic Approach 661
M. Adil Haque, John T. Bryant

VOLUME 2

Study on the Bearing Characteristics of Long-Short Piles Composite Foundation under Embankment Load 673
Yue-dong Wu, Ce-hui Shi, Jian Liu, Zhi-guo Li

GEOTECHNICAL II: TIME-DEPENDENT GEOTHERMAL ANALYSIS, EXPANDED POLYSTYRENE COMPOSITE SOIL, SODIUM SILICATE SYSTEM GROUTS, AND DREDGER FILL

Time-Dependent Geothermal Analysis—A Forensic Evaluation 682
John T. Bryant, M. Adil Haque, Brent L. Douglas

Creep Model of EPS Composite Soil and Secondary Development in FEM 692
H. M. Gao, G. X. Chen

The Rheology Properties of Peat Treated with Sodium Silicate System Grouts 700
H. Moayedi, Sina Kazemian, A. H. Vakili

The Performance of Super Soft Foundations under a Modified Vacuum Preloading Method 708
Yang Shen, Mingan Tao, Hanlong Liu, Youbin Gao, Yunliang Cui

GEOTECHNICAL III: SUBSIDENCE, STABILIZATION, SINKHOLES, AND SLOPE STABILITY

Analysis of Subsidence and Resulting Damage over an Area for 3 Decades 716
Gennaro G. Marino, Abdolreza Osouli

Stabilization of Dispersive Soils by Pozzolan	726
<i>A. H. Vakili, M. R. Selamat, H. Moayedi, H. Amani</i>	
Florida’s 2011 Sinkhole Law Revisions Provide Needed Clarity	736
<i>Mel Underwood, Neil Cichy, Robert Granica</i>	
Study on the Wind Erosion Resistance Ability and Slope Stability of a Wind-Eroded Desert Roadbed	746
<i>Chi Li, Xiaodong Ge, Hao Huang</i>	

GEOTECHNICAL IV: SOIL FAILURE, SUBSURFACE CONDITIONS, AND SOIL COMPACTION

Partial Collapse of an Ancient Masonry Church	756
<i>Nicola Augenti</i>	
Use of Forensic Engineering to Determine the Cause of a Crane Tip-Over	763
<i>E. D. Zisman</i>	
Investigation of Soil Compaction Homogeneity in a Finished Building Using Ground Penetrating Radar	773
<i>P. Anbazhagan, Deepu Chandran, Shashank Burman</i>	

HURRICANES, TORNADOES, AND EXTREME WINDS I: RESIDENTIAL DAMAGE, COMPUTATIONAL FLUID DYNAMICS SIMULATIONS, DEBRIS ASSESSMENT, AND CONDOMINIUM BUILDING DAMAGE

Study of Residential Damages in Coastal North Carolina from Hurricane Irene	783
<i>Michael P. Lester</i>	
Computational Fluid Dynamics Simulations to Predict Wind-Induced Damage to a Steel Building during Hurricane Katrina	793
<i>Lloyd L. Schulman, Christopher G. DesAutels</i>	
Sifting through the Debris: Determining Damages Following Catastrophic Natural Events	801
<i>Michael Horst, Ralf Leistikow</i>	
Investigation of Hurricane Damage to a Condominium Building in Florida	811
<i>Anurag Jain, Can C. Simsir</i>	

HURRICANES, TORNADOES, AND EXTREME WINDS II: TORNADO DAMAGE SURVEY, RESIDENTIAL CONSTRUCTION, DAMAGED STRUCTURES, AND WIND SPEEDS

Findings and Recommendations of FEMA’s Mitigation Assessment Team Investigations of the Spring 2011 Tornado Outbreaks	821
<i>Erin Walsh, Scott Tezak</i>	
Damage to Residential Construction from the Tornadoes in Vaughan, Ontario, on August 20, 2009	831
<i>Murray J. Morrison, Gregory A. Kopp, Eri Gavanski, Craig Miller, Arnold Ashton</i>	
Post-Event Forensic Investigation of Damaged Structures from Strong Wind Events	841
<i>David A. VanDerostyne, Sean K. Hallet, Jason A. Nichols</i>	
Failure vs. Flight: An Experimental Study of Wind Speeds Associated with Roof Failures of Houses	851
<i>S. E. Stenabaugh, Gregory A. Kopp</i>	

INVESTIGATIVE METHODOLOGIES: FORENSIC INFORMATION MODEL, MYTHS, OVERSIMPLIFICATIONS, MISUNDERSTANDINGS, COLLAPSE MITIGATION, AND STRENGTHENING

A New Method for Managing and Presenting Façade Investigation Data	861
<i>E. Karanci, R. Nagata</i>	
Combating Myths, Oversimplifications, and Misunderstandings about the Causes of Failures	871
<i>Jonathan Wood</i>	
Current Analysis Methods and Structural Collapse Mitigation	881
<i>S. Marjanishvili, B. Katz, E. Hinman</i>	
Strengthen America	891
<i>Kenneth B. Simons</i>	

PRACTICES TO REDUCE FAILURES: IMMINENT COLLAPSE, WOOD DETERIORATION, FACADE FAILURES, AND CODE CONSIDERATIONS

Substantial Impairment vs. Imminent Collapse of Wood Structures	899
<i>Kenneth B. Simons</i>	
Deterioration of Wood Structures—Basic Forensic Considerations	907
<i>Ronald W. Anthony</i>	

Latent Building Facade Failures	918
<i>Kimball J. Beasley</i>	
The Building Code and Repairs to Damaged Structures	928
<i>Paul James Bennett</i>	

PROFESSIONAL PRACTICE I: STANDARD OF CARE, CONTRACT MANAGEMENT, EXPERT WITNESSING, AND ETHICS

The Standard of Care, Case Law, and Jury Instructions	938
<i>Joshua B. Kardon, Lloyd M. Sonenthal</i>	
Forensic Engineering Applied to Contract Management in the Construction Industry	946
<i>Sergio Palazzo</i>	
Experts Beware—The Risks of Making It Up	954
<i>T. F. Paret, G. R. Searer</i>	
Expert Witness 101: Balancing Professional Ethics with Client Desires	962
<i>D. A. Hodgin</i>	

PROFESSIONAL PRACTICE II: INTERNATIONAL PRACTICES IN EUROPEAN COUNTRIES, LATIN AMERICA, INDIA, AND ITALY

An Initial Survey of Forensic Engineering Practices in Some European Countries and the USA	973
<i>Karel Terwel, Robert Ratay, Eugen Brühwiler, Jonathan Wood, Bruno Godart, Dénes Dalmy</i>	
Forensic Engineering Education Workshops: A Review of Experiences in the U.S. and in Latin America	983
<i>Norbert J. Delatte, Paul A. Bosela, Kenneth L. Carper, Hugo Landivar, Hugo Navarro, Oswald Rendon-Herrero</i>	
The First Indo-US Forensic Engineering Workshop and Beyond	991
<i>C. Natarajan, R. Janardhanam, A. R. Rajaram, Shen-En Chen, Ryan Schmidt</i>	
The Italian Association of Forensic Engineering	997
<i>Nicola Augenti</i>	

RESEARCH AND TESTING: LASER SCANNING MICROSCOPY, RADIOGRAPHIC EVALUATION, LOAD TESTING OF SHORING SYSTEMS, AND REPAIR TECHNOLOGY

A Universal Method to Determine Crack Age in Construction Materials	1005
<i>L. Sullivan-Green</i>	
Non-Destructive Radiographic Evaluation and Repairs to Pre-Stressed Structures following Partial Collapse	1015
<i>E. M. Reis, U. Dilek</i>	
Testing of US&R Shoring Systems under Non-Ideal Conditions	1024
<i>M. Bazan, M. Engelhardt, D. Wheat, D. Hammond</i>	
Research on Disengaging Detection and Repair Technology of a Turbine Spiral Case	1034
<i>Jikai Zhou, Jianhua Li, Yunxiang Zhang, Xiaohui Ma, Xudong Chen, Shengxing Wu</i>	

RESIDENTIAL CONSTRUCTION: HAIL DAMAGE, WALL SYSTEMS, AND CABINETS

Wright House, Wrong Peril: A Case Study in Hail Damage to a Frank Lloyd Wright Residence	1044
<i>Erik L. Nelson</i>	
Comparative Study of Multi-Hazard Performance of Different Wall Systems Used in Single-Family Dwelling Construction	1053
<i>A. Memari</i>	
Differences in Cabinet Damage Exposed to Water and Water with Detergent	1063
<i>B. Davis, R. E. Moon, D. Rondy</i>	

STRUCTURAL I: STAGE FRAMING, MODELING DOUBLE-ANGLE SHEAR CONNECTIONS, TRAMWAY MODERNIZATION, AND CFRP STRENGTHENED SQUARE HOLLOW STEEL SECTION

The Indiana State Fair Collapse Incident: Anatomy of a Failure	1070
<i>Scott G. Nacheman, Kevin J. Jackson, Joelle K. Nelson, M. J. Pinto, Luis Valderruten, Aditya Bhagath</i>	
Modeling of Double-Angle Shear Connections for the Evaluation of Structural Robustness	1081
<i>Judy Liu, Joseph Main, Fahim Sadek</i>	
The Roosevelt Island Tramway Modernization Project	1091
<i>Joelle K. Nelson, Glenn G. Thater</i>	

Experimental Investigation on the Torsional Behavior of CFRP Strengthened Square Hollow Steel Section	1101
<i>N. Abdollahi Chahkand, M. Z. Jumaat, N. H. Ramli Sulong, M. R. Mohammadizadeh, A. Asadi, M. Mojarad</i>	

STRUCTURAL II: STEEL SPACE FRAME, LOW-CYCLE FATIGUE IN STEEL STRUCTURES, LIGHT GAGE STEEL, AND STEEL MOMENT FRAMES

Thermal Load-Induced Failure of a Steel Space Frame Structure	1111
<i>B. McDonald, J. P. Hunt</i>	
The Effects of Low-Cycle Fatigue in Steel Structures	1121
<i>Navid Nastar, Gregg Brandow, James Anderson, Robert Nigbor</i>	
Failures of Light Gage Steel Structural Framing	1131
<i>David B. Peraza</i>	
Considerations on Buckling and Lateral Bracing Issues with an Emphasis on Steel Moment Frames in Seismic Areas	1139
<i>Peter Maranian, Robi Kern, Ashwani Dhalwala</i>	

STRUCTURAL III: POST-TENSIONED CONCRETE, NON-DESTRUCTIVE TESTING, AND CARBONATION

Practical Evaluation of Two-Way Slabs with Distressed PT Strands	1149
<i>K. Gatto, Z. Martin, R. A. Dethlefs</i>	
Non-Destructive Evaluation and Laboratory Testing of a Concrete Structure Damaged by Fire	1159
<i>E. M. Reis, U. Dilek</i>	
Effect of Surface Treatments and Texture on the Carbonation Rates of Fly Ash Concretes for Crack Dating	1167
<i>L. Sullivan-Green</i>	
Comparison of Non-Destructive Testing Findings to Laboratory Testing Findings from a Concrete Wall with Strength Deficiencies	1177
<i>E. M. Reis, U. Dilek</i>	

STRUCTURAL IV: CONCRETE GARAGE WITH PRECAST FORMWORK, HISTORIC HIGH-RISE REINFORCED CONCRETE BUILDING, LINEAR ELASTIC FINITE ELEMENT ANALYSIS, AND CONCRETE PODIUM SLAB

Collapse Investigation of a Concrete Garage with Precast Formwork	1186
<i>Matthew J. Sheehan, W. Gene Corley</i>	
Evaluation of a Historic High-Rise Reinforced Concrete Building	1198
<i>James S. Cohen</i>	
Identification of Reinforced Concrete Failure Modes Using Linear Elastic Finite Element Analysis	1208
<i>James B. Deaton, Lawrence F. Kahn</i>	
Investigation and Remedial Strengthening of a Concrete Podium Slab	1218
<i>R. Scott Silvester, Nicholas J. Palumbo, Charles J. Russo</i>	

STRUCTURAL V: PREFABRICATED AND HISTORIC WOOD TRUSSES, TERMITES, AND NON-DESTRUCTIVE TESTING

Prefabricated Wood Truss Roof Failure under Wind Induced Loads	1228
<i>Behnam Arya, Anurag Jain</i>	
Case Study: Failure and Repair of Historic Wood Trusses at St. John the Baptist Church (Hoboken, NJ)	1238
<i>Jaret Lynch, Joseph Bukovec</i>	
Structural Evaluation and Repair of Formosan Termite Damage in Wood Structures: Lessons Learned and Two Case Studies	1247
<i>Jason D. Gregorie</i>	
Closing the Gap between Wood NDT Technologies and Repair Methodologies	1257
<i>Janelle L. Leafblad, Paul E. Oyen</i>	

STRUCTURAL VI: WIND, SNOW, AND APPLIED LOAD FAILURES

An Investigation of the Collapse of the Dallas Cowboys Practice Facility	1268
<i>Christopher Trautner, Rasko Ojdrovic, Benjamin W. Schafer, Nicholas P. Jones</i>	
Case Study: Failure at an Abutting Lower Roof Due to Snowdrift	1278
<i>Jed B. Larsen, M. DeLeon, D. Ahuja</i>	

Investigation of the Effect of Wind on Nettings	1288
<i>Dan Eschenasy</i>	
A Case Study on the Collapse of Industrial Storage Racks	1297
<i>James P. Plantes, D. Ahuja, Ryan T. Chancey</i>	

**STRUCTURAL VII: UNDERMINING, BUILDING SETTLEMENT, ADJACENT CONSTRUCTION,
AND PRE-CONSTRUCTION SURVEYS**

How Was a SoHo Building Undermined?	1309
<i>Benjamin Lavon, Carl J. Schoenberger</i>	
Assessment of a Building Settlement and the Litigation Process—A Case Study	1318
<i>Ming Zhu, T. Bart Gary, Robert C. Bachus</i>	
Case Study: Property Damage from Adjacent Construction	1328
<i>James S. Cohen, Frank J. Giliberti, Jeffrey Migdalen</i>	
Best Practices for Conducting Pre-Construction Surveys: Lessons Learned from Construction Claims	1338
<i>Anthony M. Dolhon, David B. Peraza, Ibrahim Erdem, Rahul Ratakonda</i>	
Author Index	