

Forensic Engineering 2018

Forging Forensic Frontiers

Proceedings of the Eighth Congress on Forensic Engineering

Austin, Texas, USA

29 November - 2 December 2018

Volume 1 of 2

Editors:

Rui Liu

Alicia E. Diaz de Leon

Michael P. Lester

Michael J. Drerup

ISBN: 978-1-5108-7553-1

Printed from e-media with permission by:

Curran Associates, Inc.
57 Morehouse Lane
Red Hook, NY 12571



Some format issues inherent in the e-media version may also appear in this print version.

Copyright© (2018) by American Society of Civil Engineers
All rights reserved.

Printed by Curran Associates, Inc. (2019)

For permission requests, please contact American Society of Civil Engineers
at the address below.

American Society of Civil Engineers
1801 Alexander Bell Drive
Reston, VA 20191
USA

Phone: (800) 548-2723
Fax: (703) 295-6333

www.asce.org

Additional copies of this publication are available from:

Curran Associates, Inc.
57 Morehouse Lane
Red Hook, NY 12571 USA
Phone: 845-758-0400
Fax: 845-758-2633
Email: curran@proceedings.com
Web: www.proceedings.com

Contents

Building and Forensics Education

Cold Liquid-Applied Reinforced Membrane Roofing Application over Historic Beaux-Arts Substrates	1
Jason D. Gregorie	
Commercial Roofing Condensation—Lessons Learned	12
James W. Jordan, Ross A. Kimble, and Andrew J. Sharer	
Hidden Moisture in Low Slope Roof Systems: Can Lead to Structural Failure	23
Carl J. Schoenberger and Joseph A. Kraus	
Hail Impact Effects on the Wind Uplift Resistance of Fully Adhered Single-Ply Roof Membranes	31
Justin Donaldson, Marco DeLeon, and Kyle J. Savage	
Refuting the Presumption of Hurricane-Caused Water Intrusion.....	41
Jeffrey M. Wilemon and Robert Mulcahy	
Wind-Induced Damage to Rooftop Solar Arrays and Roofs	53
C. Can Simsir and Anurag Jain	
Mid-Rise Wood Frame Construction: A Good Idea or Are We Asking for Trouble?	62
Derek A. Hodgkin	
Building System Failures Due to Improper Interaction—Understanding How Mechanical Systems and Building Enclosures Must Work Together	73
Sean M. O’Brien, Amrish K. Patel, and Brienna E. Rust	
Forensic Evaluation and Repair of Failures in 41-Story Granite Façade.....	83
William D. Bast, Rachel Michelin, Benjamin Pavlich, and Lee Fink	
Wind-Induced Cracks in Gypsum Board Wall Panels	97
B. East	
Elastomeric Coatings: A Qualitative Failure Analysis	106
N. Alrafie, R. E. Moon, and M. Bass	
Heads Up—Flashing Ahead.....	117
Robert Bateman	
Discoloration of Glass Panel Sealants.....	128
Rui Liu and Peter Marks	

Duration of Loss: Carpet Tack Deterioration over an Eight-Year Wetting Period.....	136
Donald E. Nehrig, Ralph E. Moon, and Chin S. Yang	
Impact of Adjacent Construction on Existing Building.....	149
A. Jain and B. Arya	
Forensic Engineering, the Heart in the Life Cycle of Structural Damage: From Emergency Response through Restoration to Final Repairs.....	162
Alfredo E. (Al) Bustamante and Douglas L. Fell	
Sill Crazy—After All These Years.....	172
Robert Bateman	
Structures Built over Crawl Spaces Develop Condensation Moisture and Mold Due to Improper Construction Techniques Not in Compliance with Building Code Requirements Necessary for Adequate Performance	183
Mel A. Underwood, Steven J. Faupel, and Andrew W. Johnson	
Failures All around Us: Use of Student-Identified Failure Case Studies to Teach the Investigation Process.....	194
Tara L. Cavalline, Courtney S. Green, and Nicholas Tymvios	
Graduate Course in Forensic Engineering via Distance Education.....	207
David W. Dinehart	
International Activities of the Forensic Engineering Division.....	218
Norb Delatte	
Use of Forensic Case Studies in a Mechanics Course to Highlight the Importance of Material Testing of Steel	224
David W. Dinehart and Shawn P. Gross	
Introducing New Framework to Capture Extreme Uncertainty in Risk Management of Landslides	235
Azadeh Mostofi and Robert B. Gilbert	
Hail Sizing: A Comparison of On-Site Data with Weather Data	248
Stewart M. Verhulst, J. Daniel Bosley, and Amanda K. Talbott	
Advanced Techniques in Railroad Engineering: Railroad Accident Causes and Innovative Prevention Techniques	259
Avinash Prasad and Indira Prasad	
<i>Forensic Investigations</i>	
Forensic Investigation of a Warehouse Roof Collapse Due to Snow Load	270
Franz N. Rad, Hamid R. Afghan, and Jeffery C. Lewis	

Investigation of Collapsed Jet Hangars	280
Ibrahim Erdem and David B. Peraza	
Building Failure Investigations—First Impression Myopia	289
Kimball J. Beasley	
Collapse of Two Steel Buildings after Snow Accumulated on Their Roofs	297
Zeno Martin and Trent Tinney	
Field Experience and Lessons Learned in Bending High-Strength Steel Reinforcement	309
Kevin Conroy, Craig C. Brown, and Neal S. Anderson	
Fitness-for-Service of Heavy Structural Steel Weldments	319
E. M. Cheifet, E. T. Schickel, and R. S. Vecchio	
Rails in Retractable Roofs: Overview of the Design Methodology and a Case Study	329
Antonio De Luca, Liling Cao, Marguerite Pinto, Elisabeth Malsch, and Tom Duffy	
Understanding Wood Moisture Movement in Diagnosing Problems with Wood-Frame Structures	336
Leonard J. Morse-Fortier	
Investigation Methodology of a Sinking Building	347
Adam Abbes Yala and William D. Bast	
No-Touch Inspections: Challenges in Non-Destructive Evaluation of Subjects That Are Buried and Underwater	355
Robert Flynn, Francesca Brando, Marguerite Pinto, and Elisabeth Malsch	
Insurance Investigation of Damaged Wood Bowstring Trusses	364
Alexandar J. Mlynarczyk	
Application of Performance-Based Fire Engineering to Existing Structures and Forensic Investigations	376
Luciana Balsamo, Reza Imani, Pierre Ghisbain, Jenny Sideri, and Ali Ashrafi	
Emergency Structural Engineering Support of a Fire Origin and Cause Analysis	386
Dan Turner and Dennis Scardino	
Evaluation of Fire Effects on Precast, Prestressed Concrete Members	396
Filippo Masetti, Gloriana Arrieta Martinez, and Sean M. O'Brien	

Fire Retardant Treated (FRT) Lumber (circa 1960 to 1980) Can Experience Sudden Structural Failure When Exposed to High Humidity	408
Joseph A. Kraus and Carl J. Schoenberger	
A Case Study of Shoring and Column Failures of a Flat Plate Reinforced Concrete Structure.....	417
Byoung-Jun Lee and J. Eric Peterson	
Observations from Forensic Investigation of the Harmon Tower	426
Navid Nastar, Gregg Brandow, and Alex Nothnagel	
Arctic Structure Forensic Study.....	437
Nicholas Triandafilou, Tom Brindley, and Mustafa Mahamid	
Hyatt Regency Skywalk Collapse: Evaluation of the Box Beam Design	447
Randall Bernhardt	
Investigation and Repair of Shear Deficiencies in Concrete Flat Plates	457
A. Shear and A. Osborn	
A Statistical Approach of Understanding the Vibration Behavior of a Concrete Slab-on-Grade in Response to the Surrounding Equipment—A Case Study Using a Remote Vibration Monitoring System.....	468
Zhengqi Li	
Investigation and Repair of a Megatall Building Transfer Mat.....	477
David Drengenber and Stephen Stacey	
Investigation, Assessment, and Repair of Cracks in Precast Bridge Slabs	490
Yunyi Zou and Steven J. Smith	
Tile Tap Method: Human and Auditory Scientific Analysis	502
Don Nehrig, Nolan Wells, Robert Mulcahy, and Ralph E. Moon	
Load Tests of Concrete Structures: Allowing the Project to Determine Test Protocol.....	512
Aaron Larosche, Michael Ahern, and Randall W. Poston	
Fitness-for-Service Assessment of In-Service Wind Turbine Towers	523
P. J. Murtagh and Robert S. Vecchio	
The Importance of Destructive Testing for Identifying Concealed Resultant Structural Damage	533
Kerry S. Lee, Gary S. Dunlap, and Amanda R. Nogay	
Material Deterioration, Fitness-for-Service Analysis, and Repair of a Steel Tank.....	545
Mustafa Mahamid, Tom Brindley, Nezar Abraham, and Nicholas Triandafilou	

Duration of Metal Corrosion: Plumbing and Construction Materials557
N. Wells, R. E. Moon, and D. Nehrig

Copper Tubing Leaks: Interpreting Evidence of Failure571
Donald Dunn and Ralph E. Moon

Professional Practice

**A Framework to Prevent Construction Failures Due to Computer-Related
Errors582**
Ilias Ortega

What Is the Standard of Care?590
Joshua B. Kardon

**Forensic Engineer's Ethical Code in the Investigation of Sinkhole Activity:
Case Studies599**
L. Millman

Construction Documents' Effects on Field Issues and Accidents609
D. Wojnowski and L. Cao

Case Studies in Engineering Liability from Flawed Design Decisions619
Michael P. Lester

**Settlement of Building Floor Slab-on-Grade Constructed on Unsuitable
Urban Fill in Chicago630**
Brett Gitskin and Danilo A. Guevarra

Forensic Engineering, a Tool for Solving Problems?639
Ramon L. Carrasquillo and David Rothstein

Failures in Construction: Learning from Everyday Forensic Engineering648
Henrietta R. Baker, Simon D. Smith, Gordon Masterton, and Bill Hewlett

**Use of the ACI 562-16 Concrete Repair Code: Assessment and Repair of
Pre-Topped Precast Double Tee Flange Connections659**
Carl J. Larosche and Jeremiah D. Fasl

Double-Tee Repairs: Three Case Studies675
Jeremiah D. Fasl and Carl J. Larosche

Failure Analysis of a Reinforced Concrete Silo684
T. Ebisch and R. Chancey

Concrete Silo Failures Due to Design Errors696
J. Chavez Sagarnaga

Implications of Uncertainty in Service Life Modeling: Example of Chloride-Induced Corrosion of Reinforcement in RC Structure	707
Sumanth Cheruku	
Energy Absorption of Cementitious Composites Incorporating Carbon Nanotubes Subjected to Low-Velocity Impact Tests	717
R. Jazaei, M. Karakouzian, B. O’Toole, J. Moon, and S. Gharehdaghi	
Evaluation and Repair of Alkali-Silica Reaction Damage to Existing Concrete Wastewater Infrastructure	726
Jeffrey Wouters	
Causation of Near-Surface ASR at Concrete Slabs-on-Grade	736
Ryan D. Kalina, Ryan T. Chancey, and Stewart M. Verhulst	
Composite Canopy Load Test, Analysis, and Retrofit.....	752
Matt DeSimone and John Cocca	
Failure Analysis of Secondary Water Piping Systems	763
S. I. Lieberman	
Snow Loads on Air Supported Structures	774
Rahul Ratakonda	
Evaluation of Vibration Damage to Structures.....	780
Randall Bernhardt	
Analysis, Measurement, and Mitigation of Stay Cable Vibrations	791
A. Jain, C. Simsir, and Partha P. Sarkar	
Forensic Investigations of Floor Vibrations	800
Charles DeVore and Andrew Hardyniec	
Remediation of Wind-Induced Building Vibrations with Modular Tuned Liquid Damper System	809
Sebastian Mendes, Pierre Ghisbain, Marguerite Pinto, and Elisabeth Malsch	
Estimating Joint Return Periods for Flooding Due to Storm Surge	818
Adam Hatzikyriakou and Ning Lin	
Using Big Data in Early Warning System of Flash Floods in Mauritius	827
Roodredevi Jhagdambi and Biao Zhong	
A Summary of Findings from FEMA’s Mitigation Assessment Team Evaluation of Texas Coastal Communities Impacted by Hurricane Harvey.....	833
Daniel Bass, Brian O’Connor, and Manuel Perotin	

Structures

Evaluation of the Structural Failure of Three Retaining Walls	846
Randall Bernhardt	
Two-Way Shear Strengthening of Cast-in-Place Lightweight Concrete Flat Slab.....	856
Connor J. Bruns, Corey J. Aumiller, and Terry R. McDonnell	
Steel Framed Parking Garage Corrosion Assessment, Structural Analysis, and Shoring Repairs.....	866
Jaret M. Lynch and Hannah E. Rakowski	
Evaluation and Mitigation of Post-Tensioned Steel Corrosion	879
David Whitmore and Tore Arnesen	
Evaluation and Strengthening of Existing Wood Framed Structure	893
Byoung-Jun Lee, Marc C. Knapp, and Gerald A. Dalrymple	
Progressive Strength Loss of Fire Retardant Treated Lumber: A Case Study	903
Carmen C. Mulea and Michael J. Drerup	
Lessons Learned from Recent Failures of Structural Timber Appurtenant Assemblies	914
W. A. Fennell and K. S. Moore	
Examination of Wood Truss Failures by Creep Rupture.....	930
Zeno Martin, Kip Gatto, Jarkko Simonen, and Kent Sasaki	
Earthquakes in Oklahoma—Adapting to a New Reality.....	940
Norb Delatte and Alex Greer	
Forensic Evaluation of Earthquake-Damaged Reinforced Concrete Shear Walls	947
Jonathan Rivera and Andrew Whittaker	
Lessons Learned from the Deadliest Earthquake of 2017: Study of Damage and the Crisis Response Preparedness	957
Hossein Ataei, Mustafa Mahamid, Didem Ozevin, and Ataollah Taghipour Anvari	
Failing Forward—Construction Failure Case Studies	967
Rui Liu, Navid Nastar, Tara Cavalline, Laura E. Sullivan-Green, Paul A. Bosela, Norbert J. Delatte, M. Kevin Parfitt, and Kenneth L. Carper	
Forensic Investigation of Aboveground Storage Tank Failures during Hurricane Harvey Using Fragility Models.....	975
C. Bernier and J. E. Padgett	

General Overview and Case Studies of Damages in Puerto Rico Due to Hurricane Maria	986
Hector J. Cruzado and Gustavo E. Pacheco-Crosetti	
Evaluation and Repair of Tornado Damage to a Large Manufacturing Plant.....	997
Kevin Mesyef, Joseph Riddle, Dan Turner, and Randall Bernhardt	
Numerical Modeling of Power Delivery and Telecommunications Infrastructure for Hurricanes Harvey and Irma	1008
Dorothy A. Reed and Shuoqi Wang	
Performance of Low-Rise Construction under Wind and Coastal Hazards during the Landfall of Hurricane Harvey	1017
T. Kijewski-Correa, J. Gong, A. Kennedy, J. A. Womble, C. S. Cai, J. Cleary, T. N. Dao, F. Leite, D. Liang, K. Peterman, C. Sun, A. Taflanidis, and R. L. Wood	
Overview of Damage Observed in Regional Construction during the Passage of Hurricane Irma over the State of Florida	1028
Jean-Paul Pinelli, David Roueche, Tracy Kijewski-Correa, Fernando Plaz, David Prevatt, Ioannis Zisis, Amal Elawady, Fred Haan, Shiling Pei, Kurt Gurley, Ashkan Rasouli, Maryam Refan, Landolf Rhode-Barbarigos, and Mohammadtaghi Moravej	
Fragility Assessment of Wind-Induced Residential Building Damage Caused by Hurricane Harvey, 2017.....	1039
David B. Roueche, Franklin T. Lombardo, Daniel J. Smith, and Richard J. Krupar III	
Performance of Structures under Successive Hurricanes: Observations from Puerto Rico and the U.S. Virgin Islands after Hurricane Maria	1049
D. O. Prevatt, D. B. Roueche, L. D. Aponte-Bermúdez, T. Kijewski-Correa, Y. Li, P. Chardon, M. Cortes, C. López del Puerto, A. Mercado, J. Muñoz, and A. Morales	
Gas Main Risk Assessment through Probabilistic Fracture Mechanics	1060
E. T. Schickel, A. D. Smyth, and J. W. Cluever	
Monitoring Temperature Differential and Volumetric Water Content between Asphalt Pavement and Subgrade Layers	1070
Wanting Wang, Angela S. Hager, Kevin L. Rens, and Carnot L. Nogueira	
Assessment of Bridge Repair with the Aid of Load Test and Acoustic Emission Monitoring.....	1080
Hang Zeng, Julie Ann Hartell, and Robert Emerson	
Bridge Collapse during Demolition	1090
David B. Peraza and Ibrahim Erdem	

Shoring Failure: Considerations for Using Multiple Levels of Ellis Shoring Posts Supported on Sloped Grade	1099
Jeffrey Dowgala, Terrence Paret, and Elide Pantoli	
The Impact of an Overpour during an Elevated Slab Placement	1109
Jeremiah D. Fasl and Carl J. Larosche	
Tropicana Parking Garage Collapse	1118
P. Bosela Jr. and P. Bosela	
Industry Standards of Ground Vibration PPV Limits and Associated Distress	1125
Carlos Garza and David P. Langefeld	
Coker Wire Rope Case Study	1134
Mark Guirguis, Slawomir Domagala, Mustafa Mahamid, Nicholas Triandafilou, and Jakub Szewczyk	
An Engineering Investigation of a Recreational Trailer Explosion at Tannehill State Park, Alabama	1147
Zuhair Ibrahim	