

Geo-Congress 2019

Embankments, Dams, and Slopes

Selected Papers from Sessions of the Eighth International Conference on Case Histories in Geotechnical Engineering

Geotechnical Special Publication Number 305

Philadelphia, Pennsylvania, USA

24 – 27 March 2019

Editors:

**Christopher L. Meehan
Sanjeev Kumar**

**Miguel A. Pando
Joseph T. Coe**

ISBN: 978-1-5108-8290-4

Printed from e-media with permission by:

Curran Associates, Inc.
57 Morehouse Lane
Red Hook, NY 12571



Some format issues inherent in the e-media version may also appear in this print version.

Copyright© (2019) by American Society of Civil Engineers
All rights reserved.

Printed by Curran Associates, Inc. (2019)

For permission requests, please contact American Society of Civil Engineers
at the address below.

American Society of Civil Engineers
1801 Alexander Bell Drive
Reston, VA 20191
USA

Phone: (800) 548-2723
Fax: (703) 295-6333

www.asce.org

Additional copies of this publication are available from:

Curran Associates, Inc.
57 Morehouse Lane
Red Hook, NY 12571 USA
Phone: 845-758-0400
Fax: 845-758-2633
Email: curran@proceedings.com
Web: www.proceedings.com

Contents

Dams and Levees

Hydraulic Fracturing in Widely-Graded Dam Core Material.....	1
Ross D. Waters, Kaley Crawford-Flett, Mark Stringer, and J. J. M. Haskell	
Capacity Restoration and Slope Stabilization of the Gull Island Confined Disposal Facility	12
Tse-Wei Chen, Ragui Wilson-Fahmy, Matthew M. Lunemann, and W. Scott Douglas	
Effects of Load History on Seepage-Induced Deformation and Associated Performance in Terms of Probability of Exceeding Limit States—Case Study of Princeville Levee	23
Rowshon Jadid, Brina M. Montoya, Victoria Bennett, and Mohammed Gabr	
Multi-Decadal Earth Dam Deformation Monitoring Using Airborne LiDAR and Structure from Motion at Lago Guajataca, Puerto Rico.....	36
Andrés F. Villarreal-Arango, K. Stephen Hughes, and Alesandra C. Morales-Vélez	
Case History: Rapid Drawdown Analysis of Village Creek Plant Levee	45
Daniel R. VandenBerge, Garry H. Gregory, and Prince Turkson	
Finite Element Modeling of Partial Penetration Well Uplift Factors	57
Andrew M. Keffer, Erich D. Guy, and Elisabeth M. Chang	
Brownsville Levee Instability.....	67
Lucas A. Walshire, Joseph B. Dunbar, Isaac J. Stephens, and Maureen K. Corcoran	
Safety Evaluation and Rehabilitation for Buxi High CFRD with Face Slab Rupture.....	76
Yao Xu, Yang Wang, and Rong Li	
Slope Stability Monitoring and Early-Warning System for Kariba Dam South Bank Slope	86
Prospect K. Motsei, Lunga Mapekula, Denis Kalumba, and Charles Chibvura	
Deformation Analysis of Ritschard Dam: A Case Study of Rockfill Compression Induced Movements	96
Masood Kafash, Tiffany Adams, Richard Davidson, Don Meyer, and Ray Tenney	

Embankment and Slope Stability

Primary and Post-Surcharge Secondary Settlements of a Highway Embankment Constructed over Highly Organic Soils: A Case History	109
Liang Chern Chow, Joseph G. Bentler, and Richard A. Lamb	
Surcharge Embankment on Marine Clayey Silt Case Study and Lessons Learned.....	119
Steven Halcomb and Sean Sjostedt	
Geotechnical Health Assessment of Roadway Embankment Using Airborne LiDAR	131
Ahmed H. Elmekati, Robert Dannenberg, and Nabil M. Ghanem	
Application of Instrumentation Monitoring and Observational Methods in Construction of a Large Embankment on Soft Ground	138
Jiaer (Jerry) Wu, Yefu Li, and Junbiao He	
Unmanned Aircraft System (UAS) Photogrammetry for Tracking Streambank Erosion and Geomorphic Change along a Protected River Corridor	150
Scott D. Hamshaw, Kristen L. Underwood, Donna M. Rizzo, Jarlath O'Neil-Dunne, and Mandar M. Dewoolkar	
Reliability-Based Stability Analysis of Fiber-Reinforced Infinite Slopes	160
Assile Abou Diab, Shadi Najjar, and Salah Sadek	
Rupture Failure Modes in Analyses of Stability of Soil and Rock Slopes.....	171
Dowon Park and Radoslaw L. Michalowski	
Design and Repair of a Reinforced Steep Slope, Pinnacle Shopping Center at Tutwiler, Birmingham, AL.....	180
Robert L. Goehring	

Landslides

Influence of Hydrologic Behavior in Assessing Rainfall-Induced Landslides.....	194
Faisal S. Ahmed and L. Sebastian Bryson	
Effects of Particle Characteristics on Impact Force from a Granular Sliding Mass on a Rigid Obstruction.....	205
Andrew Grant, Amir Ahmadipur, and Tong Qiu	
Hydrological Behavior of an Infiltration Induced Landslide in Colorado, USA	213
Alexandra Wayllace, Ning Lu, and Barbara Thunder	

Case History Summaries of Five Slope Failures: Missed Predictions and Lessons Learned.....	223
Garry H. Gregory	
Stabilization of Rainfall-Induced Slope Failure and Pavement Distresses Using Recycled Plastic Pins and Modified Moisture Barrier	237
Anuja Sapkota, Asif Ahmed, Pratibha Pandey, Md. Sahadat Hossain, and Nicasio Lozano	
Investigation, Monitoring, and Design of an Anchored Retaining Wall at the Base of a Moving Slope	247
Jason D. Ross, Michael G. Rowland, Brett A. Dreger, and Charles A. Nutt	
<i>Lessons Learned from Case Histories</i>	
Case Study—Settlement of a Hydropower Dam Structure during 2015 Gorkha Earthquake	258
Binod Tiwari, Beena Ajmera, and Vivekkumar Timbadia	
Deformation Analysis of the 233 m Shuibuya Rockfill Dam Using Breakage Mechanics	267
Xiang Zhou, Yida Zhang, and Gang Ma	
MSE Wall Global Stability and Lesson Learned	277
Timothy D. Stark, Richard Handy, and Michael Lustig	
La Conchita Landslide: Case History and Remedial Measures.....	290
Daniel Pradel	
Evaluation of the Mechanical Behavior of Shirin-Dare Earth Dam by the Numerical Analysis and Monitoring	301
Mohammad Rashidi, Reza S. Ashtiani, and Habib Rasouli	
Column-Supported Embankment: Failure and Remedy	312
Radoslaw L. Michalowski, Andrzej Wojtasik, Adam Duda, Antoni Florkiewicz, and Dowon Park	