Pipelines 2021

Construction and Rehabilitation

Proceedings of Sessions of the Pipelines 2021 Conference

Online
3 – 6 August 2021

Editors:

Duane Strayer C. Douglas Jenkins

ISBN: 978-1-7138-3491-5

Printed from e-media with permission by:

Curran Associates, Inc. 57 Morehouse Lane Red Hook, NY 12571



Some format issues inherent in the e-media version may also appear in this print version.

Copyright© (2021) by American Society of Civil Engineers All rights reserved.

Printed with permission by Curran Associates, Inc. (2021)

For permission requests, please contact American Society of Civil Engineers at the address below.

American Society of Civil Engineers 1801 Alexander Bell Drive Reston, VA 20191 USA

Phone: (800) 548-2723 Fax: (703) 295-6333

www.asce.org

Additional copies of this publication are available from:

Curran Associates, Inc. 57 Morehouse Lane Red Hook, NY 12571 USA Phone: 845-758-0400

Fax: 845-758-2633

Email: curran@proceedings.com Web: www.proceedings.com Pipelines 2021 vii

Contents

Sewer Construction

A Case Study on the City of Calgary Rangeview Sanitary Trunk Pipeline Project1 Brent N. Jones, Jesse L. Remenda, and Maureen C. Carlin
By-Pass Pumping Challenges—Large Diameter Sewers
Collaboration—A Key to Success on a Challenging Pipeline Project
DC Water Anacostia Force Main Emergency Repair
Essential Infrastructure Emergency Repair of the West Fork Interceptor36 Tom Davies and Steven E. Metzler
Trash to Treasure: How Lime Turns Bad Soils into Pipe Backfill
Sewermain Rehabilitation
A Framework for Structural Design of Geopolymer Spray Applied Pipe Lining55 Amin Darabnoush Tehrani, Zahra Kohankar Kouchesfehani, and Mohammad Najafi
Case Study from Trenchless Rehabilitation Evaluation of North McKinney Interceptor Main for North Texas Municipal Water District
Challenging Rehabilitation of a Trunk Sewer Using Sprayed Geopolymer Lining in Ontario
Paul Headland, Joseph Royer, Glenn MacIntosh, and Vin Servera
CIPP Design Reconciliation: How It Works and Why It's Important86 Adam Braun and Chris Macey
DC Water at Work: Third Party Project Impact Mitigation of a Critical Trunk Sewer through Multiagency Collaboration94 Steve Bian Getachew Melsew Eyasu Yilma and Renni Zhao

Pipelines 2021 viii

Emergent Rehabilitation of a Critically Deteriorated Force Main for New Castle County, Delaware	102
Regis Yurcich, Emily Cernic, Dave Caughlin, and Rasko Ojdrovic	103
Evaluation of CIPP Design Equation for Polymeric Spray Applied Pipe Lining Zahra Kohankar Kouchesfehani, Amin Darabnoush Tehrani, and Mohammad Najafi	112
Lessons Learned from Rehabilitation of Multiple 150-in. Diameter Siphons	123
Watkins Road Force Main Rehabilitation "Challenges and Successes" for North Charleston Sewer District	134
James C. Reigart and Jarred R. Jones	
Testing and Commissioning	
Understanding the Basics of Hydrostatic Testing of Gas and Oil Pipelines for Quality Control and Integrity Definition	144
Witness Testing for Large Equipment Assets before Commissioning Stephen Metzler and D. Michael Querry	154
Trenchless Applications	
An Overview of Cyclic Loading and Fatigue on Steel and PE Pipe during HDD Installations	150
Urso A. Campos, David E. Hall, Jonathan L. Robison, and Gary Castleberry	137
A Summary of Cased Highway Crossing Design Trends in Alberta Thomas H. Greaves	169
Application of ASCE 38-02 and Alberta Transportation <i>Utility Coordination</i> Process Manual—Deerfoot Trail Improvements	179
CFRP and CIPP Pipeline Repair Reliability—It's All in the Resin!	186
City of Hurst Replaces a Critical Sewer Interceptor Using Minimally Invasive Pipe Bursting Technology	195
Shawn M. Garcia, Duane M. Hengst, and Kyle Wroblewski	
Construction Challenges with a Large Diameter Tunnel	202

Pipe Linings Rehabilitation Methods in Gravity Conveyance Conduits
Design and Digital Performance of Steel Composite Liner (SCL) Renewal of PCCP from Full-Scale Testing and Finite Element Modeling221 Ali Alavi and Graham Bell
Harnessing Advanced Inspection Technologies to Assess Metallic Water Transmission Mains
Victor Bernal Chimal, Brandon Hildebrandt, and Justin Hebner
How Pipe Bursting Brings More Bang for Your Water Rehab Buck237 Patrick Laidlaw and George Mallakis
Inglewood Sanitary Trunk—A Case Study in Using Today's State of the Art Technologies to Provide Sewage Conveyance Capacity to Meet Tomorrow's Needs247 Patrick Ilasewich, Marvin McDonald, Chris Macey, and Melanie Gray
Large Diameter Sliplining Rehabilitation of the Groat Road Storm Trunk256 Christopher Lamont, Jason Lueke, Yang Zhang, and Zhongquan Fu
Non-Disruptive, Close-Fit Pressure Pipe Rehabilitation System Selected among Several Options for Critical Tunnel Project
Now You See It, Now You Don't: Going Trenchless in Oklahoma
Permitting and Designing an Interstate Natural Gas Pipeline River Crossing While Navigating Federal and State HDD Guidelines
Pipe Bursting for Water Line Replacement: A Case Study294 John A. Blondell
Raising the Bar—Design Approach for Steel Piping in Tunnel Shafts and Access Pits
Henry H. Bardakjian and Mark W. Bush
Thickwood Trunk Sewer—Direct Pipe Installation

Trans Mountain Employs Extensive Risk Mitigation Measures for Trenchless Construction on Their New Pipeline Expansion
James Murphy and John Zhao
Watermain Construction
Large Diameter Transmission Pipeline Construction through a Dense Urban Landscape
Denis Atwood, Kevin Tran, Ram Chakradhar, and Hasnain Jaffri
Keeping Construction Going during the COVID-19 Pandemic
San Diego County Water Authority's Rapid Response to Thrust Restraint Issues in the Second Aqueduct at Moosa Canyon
Seating, Shrinking, Surging, and Pigging—Raw Water Pipeline Design and Construction
Cameron Lawrence, Scott Maughn, and Travis Markham
Watermain Rehabilitation
Cured-in-Place Lining for Watermains: A Municipal Retrospective369 Yafei Hu
Evaluating the New Temporary Lining Repair of 4 m Diameter PCCP to Improve MMRA Phase I Pipeline Integrity
and Mostafa Rashed Mohamed Bousheha
Exploration of Loose-Fit and Tight-Fit Sliplining with Butt-Fusion Welded
Thermoplastic Piping for Pipeline Rehabilitation
Lining Steel Watermains to Allow Expansion of Rail and LRT Lines in Calgary396 George J. Bontus and Mike Luck
Minimizing Shut Down during Repair of PCCP407 G. Henry, M. Larsen, and S. Sekhon
Optimizing PCCP Rehabilitation Based on Lessons Learned during Construction of Metropolitan's PCCP Rehabilitation Program

Pipelines 2021 xi

Piloting Innovative Approaches to Pipe Structural Renewal and Monitoring	
Methods	426
John W. Norton Jr., Todd W. King, Timothy Kuhns, Gunther Berg, Logan Trifone,	
Stan Boshart, Ali Aliva, Bob St. John, Wentao Wang, Curt Wolf, and Jerome Lynch	
Rehabilitation of an 8-in. AC Water Supply Line of a Fish Hatchery at	
Lake Whatcom, Washington	436
Regina Costa and Randy Wilkinson	
Structural Renewal of a 60 in. Potable Water Transmission Main Using CFRP	
for New Jersey American Water	442
Richard D. Conklin Jr., Edward P. Gajek, Dave Caughlin, Michael Wolan, Rasko Ojdrovic, and Jeff Molesko	
Tales from the East Brampton 1,050 mm Transmission Feedermain Condition	
Assessment	450
Heather Edwards, Heather Jefferson, Allison Biggar, and Greg Beams	
Unique Challenges of Rehabilitation of 66-in. and 72-in. Water Main in the	
Heart of Washington, DC	460
Burak Kaynak and Monika Blassino	• •
— J	