

Contribution of Metallography to Production Problem Solutions

Selected peer-reviewed extended papers
abstracts of which were presented at the
15th Conference “Contribution of
Metallography to Production Problem Solutions”

Aggregated Book

Edited by

Dr. Josef Kasl

■
■ *Scientific.Net*
■

Copyright © 2022 Trans Tech Publications Ltd, Switzerland

All rights reserved. No part of the contents of this publication may be reproduced or transmitted in any form or by any means without the written permission of the publisher.

Trans Tech Publications Ltd
Seestrasse 24c
CH-8806 Baech
Switzerland
<https://www.scientific.net>

Volume 7 of
Scientific Books Collection
ISBN 978-3-0357-2694-7

Full text available online at <https://www.scientific.net>

Distributed worldwide by
Trans Tech Publications Ltd
Seestrasse 24c
CH-8806 Baech
Switzerland
Phone: +41 (44) 922 10 22
e-mail: sales@scientific.net

Printed with permission by
Curran Associates Inc. (2023)

CURRAN ASSOCIATES INC.
proceedings
.com

Additional copies of this
publication are available from:

Web: www.proceedings.com/68395.html

Table of Contents

Preface	v
Committees	vi
Chapter 1: Technological Research	
Surface Modification of Alumina Particles to Enhance Bonding Properties with Rubber and Resin in Grinding Tools	
L. Čelko, V. Bednaříková, M. Remešová, M. Casas Luna, L. Klakurková, K. Zábranský, D. Holemý and J. Švejar	3
Stabilizing the Microstructure of Additively Manufactured Low-C Co-28Cr-6Mo Alloy	
M. Roudnická, J. Kubasek, J. Bigas and D. Vojtech	9
Production and Application of Magnesium Alloys Castings	
L. Klakurková, M. Juliš, P. Gejdoš, J. Švejar and J. Cileček	15
Correlating the Microstructure with the Mechanical Behaviour of Titanium Structures Produced by Robotic Assisted Deposition	
A. Kashimbetova, S. Tkachenko, M. Remešová, A. Mata-Leija, P. Gejdoš, L. Čelko and E.B. Montúfar	22
Hardening of Rail Vehicle Axles	
S. Němeček, K. Trojan, J. Čapek, N. Ganev, I. Černý and J. Kec	27
Tribotests of Valve Seats Made of ADI and Q - Cryo Cast Iron with Spheroidal Graphite	
B. Skrbek and J. Mráz	32
Interaction of AZ91 Magnesium Alloy with Ceramic Shell during Investment Casting	
P. Gejdoš, M. Juliš, L. Klakurková and M. Dyčka	37
Microstructure of Mo-La₂O₃ Composite Powder Prepared Using Two Different High Energy Ball Milling Systems	
S. Tkachenko, L. Čelko, M. Remešová, V. Bednaříková, K. Dvořák, P. Komarov and K. Zábranský	43
Structure and Mechanical Properties of Welded Joints of Large Steel Forgings for Nuclear Power Plants of MIR 1200 Type	
S. Hermanova, J. Kosňovská and L. Kander	49
The Evaluation of Ti-24Nb-8Ta-4Sn Alloy Prepared by 3D Printing	
J. Krčil, V. Mára and J. Šimota	55
Influence of Forging Parameters on Microstructure and Properties of En AW-6082 Alloy	
V. Mára, J. Horník and R. Bednář	61
Metallographic Evaluation of Ni-Cr Cold Spray Layers on the Tube	
Z. Špirit, M. Chocholoušek and J. Brom	67
Laser Surface Hardening of Graphite Cast Iron	
J. Horník, J. Krčil, V. Mára and A. Mores	74

Chapter 2: Materials Degradation

Damage and Fracture in Creep of a Cast B1914 Superalloy

M. Kvapilová, P. Král, J. Dvořák, K. Hrbáček, K. Kuchařová and V. Sklenička 83

Influence of Processing Technology on Creep Damage of Ultrafine-Grained Titanium

J. Dvořák, P. Král, A.G. Kadomtsev, V.I. Betekhtin, M.V. Narykova, M. Kvapilová and V. Sklenička 89

Effect of Graphite on Residual Lifetime of Superheater Tubes Made of Steel 16Mo3 after Creep Exposure

Š. Stejskalová, Z. Kuboň and G. Rožnovská 95

In Vitro Corrosion Study of Selected Laser Melted WE43 Magnesium Alloy in Hank's Balanced Salt Solution

V. Bednaříková, L. Klakurková, M. Remešová, M. Horynová, J. Suchý, D. Paloušek and L. Čelko 102

Creep Damage in Steam Pipelines and the Use of Metallography in Verifying the Possibilities of Testing

P. Mareš, J. Veselá and Z. Špirit 108

Chapter 3: Failure Analysis

Causes of Injection Mould Insert Block Damage

Z. Pavloušková, L. Klakurková, M. Juliš, P. Gejdoš and J. Švejcar 117

Analysis of the Causes of Shaft Damage

K. Zábranský, L. Klakurková, P. Gejdoš, M. Juliš and J. Švejcar 123

Analysis of Cracked Rail of the Crane of Type A120

J. Kasl 129

Analysis of the Causes of Failure and Material Analysis of Components of the Screw Conveyor of a Coal Boiler for Steam Production

J. Koc, E. Chvostová and J. Dlouhý 137

Chapter 4: Production Defects

Castings Defect Analyses

M. Koukolíková 147

Analysis of the Causes of Increased Reject Rate in Connecting Rod Production

P. Martínek and J. Vokáč 153

Analysis of Defects Associated with Manufacturing Keys for Brass Musical Instruments

D. Bricin, J. Odehnal, A. Kříž and Z. Špirit 160

Analysis of a Damaged Drill Made from Hs 2-9-1-8 Steel

V. Průcha, D. Bricin and J. Hájek 166

Chapter 5: Testing and Examination Methods

Application of Metallographic Investigation in Development of Sub-Sized Specimen Testing Techniques

E. Chvostová, P. Konopík and P. Martínek 175

Characteristics of Metallographic Preparation of Heat Exchanger Austenitic Stainless Steels	
L. Pilsová, V. Mára, M. Svobodová and J. Horváth	181
Replicas Application in Non-Destructive Testing	
J. Veselá, P. Zahrádka and J. Matějčíček.....	187
Keyword Index	193
Author Index	195