

# **Highway 1 Rat Creek Embankment Failure**

**2021 Reconnaissance and Analysis**

**Geotechnical Special Publication No. 337**

**Editors:**

**Dimitrios Zekkos  
Timothy D. Stark**

ISBN: 978-1-7138-8404-0

**Printed from e-media with permission by:**

Curran Associates, Inc.  
57 Morehouse Lane  
Red Hook, NY 12571



**Some format issues inherent in the e-media version may also appear in this print version.**

Copyright© (2023) by American Society of Civil Engineers  
All rights reserved.

Printed with permission by Curran Associates, Inc. (2023)

For permission requests, please contact American Society of Civil Engineers  
at the address below.

American Society of Civil Engineers  
1801 Alexander Bell Drive  
Reston, VA 20191  
USA

Phone: (800) 548-2723  
Fax: (703) 295-6333

[www.asce.org](http://www.asce.org)

**Additional copies of this publication are available from:**

Curran Associates, Inc.  
57 Morehouse Lane  
Red Hook, NY 12571 USA  
Phone: 845-758-0400  
Fax: 845-758-2633  
Email: [curran@proceedings.com](mailto:curran@proceedings.com)  
Web: [www.proceedings.com](http://www.proceedings.com)

# Contents

Preface.....	vii
List of Participants and Authors.....	ix
Acknowledgments.....	xi
List of Figures.....	xiii
List of Tables.....	xxi
<b>Chapter 1 Executive Summary.....</b>	<b>1</b>
<b>Chapter 2 Brief Description of the Performance of Highway 1 System during the January 27 to 28, 2021, Precipitation Event .....</b>	<b>5</b>
2.1 Highway 1 System Performance .....	5
2.2 Highway 1 Failure at the Rat Creek Drainage Crossing.....	16
<b>Chapter 3 Geographic and Geologic Setting.....</b>	<b>19</b>
3.1 Rat Creek Geology .....	23
References .....	25
<b>Chapter 4 Brief Big Sur Highway 1 History .....</b>	<b>27</b>
4.1 Big Sur Highway 1 History as a System.....	27
4.2 Rat Creek Section History and Performance .....	28
References .....	33
<b>Chapter 5 Data Collection Activities .....</b>	<b>35</b>
5.1 Prefailure Data and Geometries.....	35
5.2 February 25, 2021, Site Activities.....	36
5.2.1 Terrestrial Light Detection and Ranging Acquisition .....	37
5.2.2 Exposure Mapping and Sampling.....	37
5.2.3 Radiocarbon Dating of Exposure Samples.....	38
5.3 Satellite-based Assessments .....	41
References .....	44
<b>Chapter 6 2020 Dolan Fire.....</b>	<b>45</b>
References .....	48

<b>Chapter 7 Climate and Precipitation .....</b>	<b>49</b>
7.1 General Climate and Precipitation History of Big Sur, California .....	49
7.2 January 26 to 28, 2021, Precipitation Event.....	51
References .....	59
<b>Chapter 8 Tree Debris Dam Formation and Breach .....</b>	<b>61</b>
<b>Chapter 9 Debris Flow.....</b>	<b>69</b>
9.1 Photographic Record along the Debris Flow Path at Rat Creek.....	74
<b>Chapter 10 Upstream Collection Basin and Debris Volumes .....</b>	<b>83</b>
10.1 Size of Upstream Collection Basin.....	83
10.2 Calculation of the Amount of Water Reaching Highway 1 .....	87
Reference .....	91
<b>Chapter 11 Overtopping of Highway 1 and Embankment Erosion .....</b>	<b>93</b>
<b>Chapter 12 2021 Rat Creek Roadway Repair.....</b>	<b>95</b>
References .....	100
<b>Chapter 13 Summary and Recommendations.....</b>	<b>101</b>
<b>Index.....</b>	<b>103</b>