

7th International Conference on Structural Integrity and Durability (ICSID 2023)

Procedia Structural Integrity Volume 58

Dubrovnik, Croatia
19-22 September 2023

Editors:

**Željko Božić
Siegfried Schmauder
Katarina Monkova**

**George Pantazopoulos
Sergio Baragetti
Francesco Iacoviello**

ISBN: 978-1-7138-9891-7

Printed from e-media with permission by:

Curran Associates, Inc.
57 Morehouse Lane
Red Hook, NY 12571



Some format issues inherent in the e-media version may also appear in this print version.

Copyright© (2023) The Authors. Published by Elsevier Ltd.
Creative Commons Attribution 4.0 International License.
License details: <http://creativecommons.org/licenses/by-nc-nd/4.0/>.

No changes have been made to the content of these proceedings. There may be changes to pagination, and minor adjustments for aesthetics.

Printed with permission by Curran Associates, Inc. (2024)

For permission requests, please contact the publisher:

Elsevier B.V.
Radarweg 29
Amsterdam 1043 NX
The Netherlands

Phone: +31 20 485 3911
Fax: +31 20 485 2457

<http://www.elsevierpublishingsolutions.com/contact.asp>

Additional copies of this publication are available from:

Curran Associates, Inc.
57 Morehouse Lane
Red Hook, NY 12571 USA
Phone: 845-758-0400
Fax: 845-758-2633
Email: curran@proceedings.com
Web: www.proceedings.com

TABLE OF CONTENTS

Preface	1
<i>Željko Božić, Siegfried Schmauder, Katarina Monkova, George Pantazopoulos, Sergio Baragetti, Francesco Iacoviello</i>	
Experimental Testing of Ti-6Al-4V Under Axial Cyclic Loading	3
<i>Emanuele Vincenzo Arcieri, Sergio Baragetti, Željko Božić</i>	
Impact of Microstructure Morphology on Fatigue Crack Initiation in 9Cr-1Mo (P91) Through Numerical Simulation.....	9
<i>M. R. A. Rahim, S. Schmauder, Y. H. P. Manurung, Ž. Božić, P. Binkele, J. Dusza, T. Csanádi, M. I. M. Ahmad, M. F. Mat, K. J. Dogahe</i>	
I+II Mixed Mode Fatigue Crack Propagation Under Combination of Tensile Loading and Corrosion in a HSS Specimen	17
<i>Lucie Malíková, Pavel Doubek, Vít Křivý, Stanislav Seitl</i>	
Design and Fracture Mechanics of Lithium-Ion Batteries.....	23
<i>Davide Clerici, Francesca Pistorio, Aurelio Somà</i>	
Compression Behavior of Diamond Cellular Structure Made of Inconel 718.....	30
<i>Katarina Monkova, George Pantazopoulos, Peter Pavol Monka, Anagnostis Toulfatzis, Peter Baron, Sofia Papadopoulou</i>	
How Many Critical Planes? A Perspective Insight into Structural Integrity.....	35
<i>A. Chiocca, M. Sgamma, F. Frendo</i>	
Fatigue Life of Damaged Wing-Fuselage Fitting	42
<i>Aleksandar Grbovic, Abdussalam Solob, Zeljko Bozic, Simon Sedmak, Aleksandar Sedmak</i>	
Corrosion Resistance and Other Utility Properties of Selected Austenitic Nodular Cast Irons.....	48
<i>Alan Vaško, Viera Zatkáliková, Juraj Belan, Milan Uhříek, Václav Kača</i>	
Design Examination, Failure Analysis and Repair of the Discharge Boom Suspension of the Bucket Wheel Excavator	54
<i>W. Dudziński, P. Moczek, Piotr Odyjas, Maciej Olejnik, Damian Pietrusiak, Jędrzej Więckowski</i>	
Finite Element Validation and Model Updating of Beam in Agricultural Mower for Fatigue Assessment	61
<i>J. R. Steengaard, A. P. K. Holm, V. Arora, M. L. Larsen</i>	
Corrosion vs. Fatigue in a High-Strength Steel Specimen Investigated via FEM.....	68
<i>Lucie Malíková, Anna Benešová, Mohammad Al Khazali, Stanislav Seitl</i>	
Finite Element Validation and Non-Proportionality Quantification of Lifting Arm for Agricultural Mower Based on Experimental Results.....	73
<i>Mikkel L. Larsen, Joachim D. Gensmann, Alexander P. K. Holm, Vikas Arora</i>	
Knowledge Base for Fatigue Life Evaluation of Bodyworks of Buses, Trolley-Buses, and Battery-Buses	80
<i>Radovan Minich, Miloslav Kepka Jr., Miloslav Kepka</i>	

Integrity Assessment of a Crack Inside a Pressure Vessel Wall in RHPP “Bajina Bašta”	87
<i>Mirjana Opaèia, Simon Sedmak, Aleksandar Sedmak, Lazar Jeremia, Nikola Milovanovia</i>	
New Methods to Increasing Efficiency for Durability Design of Elastomeric Bushings	95
<i>Kay Büttner, Steven Ernst, Eric Töpel, Thomas Thüringer, Tobias Wegewitz, Günther Prokop</i>	
System Identification Based Structural Damage Aggravation Detection in a Large Masonry Building	102
<i>Dipendra Gautam, Simon Olafsson, Rajesh Rupakhety</i>	
Quantification of Structural Components of Alloy 718 and Their Effect on Dynamic Mechanical Properties.....	109
<i>Juraj Belan, Milan Uhríèik, Alan Vaško, Lucia Pastierovièová, Eva Tillová, Silvia Hudecová</i>	
An Open-Source Moose Implementation of Phase-Field Modeling of Fracture in Functionally Graded Materials	115
<i>P. C. Sidharth, B. N. Rao</i>	
Application of EMI Technique in Crack Propagation Under the Block Loading Conditions for AA6061 Alloy	122
<i>K. N. Pandey, Gurkirat Singh</i>	
Failure Mechanisms of Hexagonal-Shaped Intra-Module Connections in Modular Steel Building	130
<i>Yazmin Sahol Hamid, Hazrina Mansor, Mohamad Zarif Mirza Alias, Nurul Hidayah Saberi, Norazlinda Elisa Alias</i>	
Analysis of Energy Dissipation in Non-Linear Viscoelastic Beam in Skew Bending	137
<i>Victor Rizov</i>	
Effects of Creep of the Salt Rock Formation on the Failure of Cement Sheath Integrity.....	144
<i>Heng Yang, Yuhuan Bu, Shaorui Jing, Lingyun Zhao, Shenglai Guo, Huajie Liu</i>	
The Damping Problem in Non-Linear Viscoelastic Frames Under Varying Temperature	150
<i>Victor Rizov</i>	

Author Index