

# **4th Conference on Geophysics for Infrastructure Planning, Monitoring and BIM 2025**

Held at Near Surface Geoscience Conference & Exhibition  
(NSG2025)

Naples, Italy  
7-11 September 2025

ISBN: 979-8-3313-3223-5

**Printed from e-media with permission by:**

Curran Associates, Inc.  
57 Morehouse Lane  
Red Hook, NY 12571



**Some format issues inherent in the e-media version may also appear in this print version.**

Copyright© (2025) by the European Association of Geoscientists & Engineers (EAGE)  
All rights reserved.

Printed with permission by Curran Associates, Inc. (2026)

For permission requests, please contact by the European Association of Geoscientists & Engineers (EAGE)  
at the address below.

European Association of Geoscientists & Engineers (EAGE)  
PO Box 59  
3990 DB Houten  
The Netherlands

Phone: +31 88 995 5055

Fax: +31 30 634 3524

[eage@eage.org](mailto:eage@eage.org)

**Additional copies of this publication are available from:**

Curran Associates, Inc.  
57 Morehouse Lane  
Red Hook, NY 12571 USA  
Phone: 845-758-0400  
Fax: 845-758-2633  
Email: [curran@proceedings.com](mailto:curran@proceedings.com)  
Web: [www.proceedings.com](http://www.proceedings.com)

## TABLE OF CONTENTS

Impact of Reinforced Concrete Sleeper on Ground Penetrating Radar Signal Behavior in Railway Ballast Monitoring..... <i>S. Harajchi, E. Slob</i>	1
Clustering and Petrophysics of Combined Resistivity and Seismic Measurements for River Embankments Screening. .... <i>A. Vergnano, C. Comina, H. Yan, D. Chieppa, C. Deangeli, L. V. Socco</i>	6
A 4 Km Combined Seismic and Electric Streamer Survey Along an Embankment of the Po River. .... <i>C. Comina, A. Vergnano, A. Arato, M. Naldi, T. Bigini, D. Chieppa, L. V. Socco</i>	11
Modal Analysis of Structures by Means of Optical Methods ..... <i>S. Castellaro</i>	16
Application of MEMS Gravity Sensors to Detect Underground Hazards at the Global Centre for Rail Excellence..... <i>F. Neill, M. Reed, J. Wingate, N. Metje, D. Boddice</i>	21
Surface Wave Phase Velocity Uncertainties Analysis on Roadside DAS: Influence of Cable and Ground coupling..... <i>I. Gaudot, A. Bitri, F. Bretaudeau, D. Leparoux, M. Lehujeur, M. Leroy</i>	26
Verifying Jet Grouting Consolidation Through 3D Seismic Tomography: A Viaduct on the Naples-Bari Railway..... <i>M. Taddeo, A. Montanaro, G. Esposito, D. Fiore, V. Naclerio</i>	31
Comparative Study of Non-Invasive Electrodes for Urban Electrical Resistivity Tomography Applications..... <i>T. Debouny, D. Caterina, H. Michel, F. Nguyen</i>	36
Long-Term Dynamic Monitoring for Structural Health Assessment of Bisantis Bridgecandela..... <i>F. Mittiga, S. Candela, D. Fiore, P. De Lellis</i>	41
3D DCIP Techniques for Detection of Internal Defects in the Älvkarleby Test Dam ..... <i>R. Norooz, T. Dahlin</i>	46
Integrated Geophysical Investigation for Embankment Stability Analysis in Comacchio Valley (FE), Italy ..... <i>G. Travan, F. Accaino, A. Affatato, L. Baradello, E. Barison, A. Bratus, F. Da Col, M. Giorgi, S. Picotti, O. Souza De Araujo, A. Travan, G. Farina, M. Monti</i>	51
Identifying and Monitoring Potential Seepage Pathways in Earth Dams Using Geoelectrical Timelapse Imaging Technology..... <i>M. Cimpoiasu, J. Boyd, O. Kuras, P. Wilkinson, P. Meldrum, S. Butler, J. Chambers</i>	56
Continuous Geophysical Monitoring in a Railway Setting: A Four-Year Case Study. .... <i>L. Vivin, T. Bardainne, N. Deladerriere, C. Cai, R. Tarnus, J. Boisson Gaboriau, A. Hallier</i>	61
Tree Roots Detection with Ground-Penetrating Radar Under Different Types of Pavements: Case Study in Braga, Portugal..... <i>A. G. Gereia, A. E. Mihai</i>	66

Near-Surface Full-Waveform Inversion of DAS Data—a Case Study from an Alpine Landslide .....	71
<i>F. Rincón, S. Noe, M. Aleardi, T. Kiers, C. Schmelzbach, A. Tognarelli, E. Stucchi, A. Fichtner</i>	
Characterisation of Innovative Backfilling Grout Containing By-Products for Mechanised Tunnelling Via Ultrasonic Pulse Velocity .....	76
<i>D. Zanti, F. Pace, C. Todaro, D. Peila, A. Godio</i>	
Traffic Induced Noise Analysis for River Embankment Monitoring.....	81
<i>D. Chieppa, C. Comina, A. Vergnano, L. V. Socco</i>	
Monitoring Railway Infrastructure in Norway Using Geophysics and Distributed Acoustic Sensing: The Bolstadstrandi Case Study.....	86
<i>L. Dalaijargal, I. Lecomte, B. O. Ruud, P. J. Thomas</i>	
Modelling and Installation of Underwater Electrodes for ERI Seepage Monitoring at an Embankment Dam .....	91
<i>B. Ogden, K. Butler, P. Lelievre, J. Ball</i>	
Evaluation of Ground Improvement Techniques Using Surface Wave Methods.....	96
<i>A. Tijera, A. Santamaría, J. Estaire, M. Santana</i>	

**Author Index**